

MATERIAL SAFETY DATA SHEET

333 Hollenbeck St.
 Rochester NY 14621
 Information: 585-336-2200

Emergency Phone:
 INFOTRAC: 1-800-535-5053
 OUTSIDE US: 1-352-323-3500

PRODUCT NAME: ENVIRO CARE, Resilient Tile Coating

REVISION DATE: 03/10/2003 REVISION NUMBER: 3
 DATE PRINTED: 03/10/2003 PREPARED BY: EH&S DEPARTMENT

1. CHEMICAL PRODUCT

MSDS FORM NUMBER: 7064
 NFPA/HMIS HAZARD CODES (minimal=0; slight=1; moderate=2; serious=3; severe=4)

Health: 0/1
 Fire: 0/0
 Reactivity: 0/0
 Special/Protective None/B
 Equipment:

2. COMPOSITION/INFORMATION ON INGREDIENTS**Hazardous Components**

PRODUCT COMPOSITION CAS REGISTRATION NO.	APPROX. WEIGHT PERCENT	ACGIH TLV	ACGIH UNIT	OSHA PEL	OSHA UNIT	SARA 313 Reportable
Diethylene glycol methyl ether 111-77-3	5.2	NA	NA	NA	NA	Yes Certain Glycol Ethers Category
Tributoxy ethyl phosphate 78-51-3	1.8	NA	NA	NA	NA	No

3. PHYSICAL AND CHEMICAL PROPERTIES

BOILING POINT (F): 212 F (C) NA
 VAPOR PRESSURE: NE
 VAPOR DENSITY (AIR=1): NE
 SOLUBILITY IN WATER: MISCIBLE
 SPECIFIC GRAVITY: 1.020 (8.5 lbs./gal.)
 VOC Content (%): 5.14 (EPA Method 24)
 VOV Content (%): NE
 EVAPORATION RATE: NE
 PH: 8.5
 APPEARANCE AND ODOR: Opaque white liquid. Mild acrylic odor.

4. FIRE AND EXPLOSION HAZARD DATA

ENVIRO CARE, Resilient Tile Coating

FLASH POINT (F): None (TCC) (C): NA

METHOD: TCC

EXTINGUISHING MEDIA: As for surrounding fire. Product will not burn.

FIRE FIGHTING PROCEDURES: None.

5. STABILITY AND REACTIVITY

STABILITY DATA: STABLE

POLYMERIZATION: Will Not Occur.

HAZARDOUS DECOMPOSITION: None

INCOMPATIBILITY (MATERIALS TO AVOID): None

CONDITIONS/HAZARDS TO AVOID: None.

6. HAZARDS IDENTIFICATION

EFFECTS FROM ACUTE EXPOSURE:

INGESTION:

May be harmful if swallowed.

SKIN CONTACT:

May cause moderate skin irritation.

INHALATION:

Inhalation of spray mist may be irritating.

EYE CONTACT:

May cause moderate eye irritation.

CHRONIC EFFECTS:

None known.

EFFECTS/CARCINOGENICITY:

None listed under OSHA, IARC, or NTP.

ROUTES OF ENTRY:

Routes of entry for solids and liquids include eye and skin contact, ingestion and inhalation.

EMERGENCY AND FIRST AID MEASURES:

INGESTION: Contact Physician. **SKIN:** Wash with soap and water. **INHALATION:** Move person to fresh air. **EYES:** In case of contact, immediately flush eyes with plenty of water for at least 15 minutes and get medical attention if irritation persists.

ENVIRO CARE, Resilient Tile Coating

NOTES TO PHYSICIAN: None.

7. HANDLING AND STORAGE

SPILL PROCEDURES:

SMALL SPILLS: Reclaim as much as possible.

LARGE SPILLS: Dike to contain. Pick up with absorbant material. Put in suitable container for disposal. Flush remainder with water.

WASTE DISPOSAL METHODS:

Dispose in accordance with Federal, State and Local regulations.

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE:

Caution: Avoid contact with skin and eyes. Avoid prolonged contact. Use only in a well ventilated area. Keep from freezing.

OTHER PRECAUTIONS:

Keep out of reach of children.

8. EXPOSURE CONTROLS/PERSONAL PROTECTION

EXPOSURE CONTROLS: None known.
RESPIRATORY PROTECTION: None required.
PROTECTIVE GLOVES: Rubber gloves.
EYE PROTECTION: Safety Glasses.
OTHER PERSONAL PROTECTION: None.
EQUIPMENT:
VENTILATION: None required.

Health and safety information presented on this form is generally applicable at recommended dilutions, varying only in degree. This information was compiled from current, reliable sources and is believed to be correct. As data, and/or regulations change, and conditions of use and handling are beyond our control, no warranty, express or implied, is made as to completeness or continuing accuracy of this information.

*** END OF MSDS ***